	Type	L #	Hits	Search Text	DBs	Time Stamp	Comments	Error or Definition	Errors
1	BRS	L2	91694	transceiver	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	2005/03/17 12:25			
2	BRS	L3	11	1 and 2	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	2005/03/17 12:25			
3	BRS	L1	361	double near data near rate near memory	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	2005/03/17 12:38			
4	BRS	L4	2	framer same transceiver same decapsulate	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	2005/03/17 12:39			
5	BRS	L5	314	framer same transceiver	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	2005/03/17 12:39			
6	BRS	L6	151	331/180.ccls.	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	2005/03/17 13:13			
7	BRS	L7	750	331/179.ccls.	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	2005/03/17 13:13			
8	BRS	L8	428	331/36C.ccls.	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	2005/03/17 13:17			
9	BRS	L9	1878	331/17.ccls.	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	2005/03/17 13:17			

	Type	L #	Hits	Search Text	DBs	Time Stamp	Comments	Error Definition	Errors
10	BRS	L10	800	331/177v.ccls.	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	2005/03/17 13:17			
11	BRS	L11	1280	327/156.ccls.	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	2005/03/17 13:17			
12	BRS	L12	530	327/157.ccls.	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	2005/03/17 13:18			
13	BRS	L14	30405	switch$3 near capacit$4	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	2005/03/17 13:19			
14	BRS	L15	24502	pll and oscillator	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	2005/03/17 13:19			
15	BRS	L16	855	14 and 15	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	2005/03/17 13:21			
16	BRS	L17	192	(6 7 8 9 10 11 12) and 16	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	2005/03/17 13:21			